

clamp is designed for mounting CS-05 series sensor on round cylinder.







Step 2





Step 1
Loosen screw & nut.

Place sensor & wrap the band around the cylinder, Position the hook with the nearest hole on the band and mark the hole with a permanent marker.

Step 3

Remove mounting assembly. Cut the band at the nearest edge of next hole. (the one that's further away from the mounting head).

Step 4

Re-place the sensor & mounting assembly. Wrap the band & put the chosen hole on hook. Position the switch and tighten. Finally swivel nut for steadying.



BK - 81: For ϕ 6 ~ ϕ 32 round cylinder use .

BK - 82: For ψ 6 ~ ψ 63 round cylinder use.