

# Electromechanical Automation Product Discontinuance



**Bulletin #** SD1380  
**Date:** Friday, July 12, 2013  
**To:** All Master Price List Holders  
**Product:** OEMZL4 Drive and OEMZL6104 Drive/Controller  
**Subject:** OEMZL4 and OEMZL6104 Drive and Drive/Controller Obsolescence

## Obsolescence of OEMZL4 Drive and OEMZL6104 Drive/Controller

Parker Hannifin, EMN – Rohnert Park is discontinuing the sale of the following power levels of the OEMZL drive and drive/controller family, effective immediately:

*OEMZL4*

*OEMZL6104*

Due to low sales and difficulty in sourcing key components, EMN can no longer support the production of this drive and drive/controller. Replacement products can be directly implemented in the same applications, so no last-time buy is required. **This will not affect the OEMZL6 product line.**



## Suggested Replacements

Parker recommends the following replacements:

Current Product	Suggested Replacement
OEMZL4	ZETA4
OEMZL6104	ZETA6104

Please note that the ZETA replacements have all of the functionality of the OEMZL product plus Active Damping, Electronic Viscosity and Following capabilities. This information can also be found at [www.parkermotion.com](http://www.parkermotion.com) under our FAQ section:

<http://www.parkermotion.com/dmxreadyv2/faqsmanager/faqsmanager.asp?question=182>

If you have any questions, please contact:

- Technical Assistance, Applications Engineering Department (e-mail: [emn\\_support@parker.com](mailto:emn_support@parker.com) or call 800-358-9070 North America, 707-584-7558 International)

**Note: All information contained in this bulletin is proprietary and not intended for unauthorized distribution.**